

M-984-02S



Images are for reference only.
See Product Specifications for product details.
Buy M-984-02S with confidence from Component-World.HK, 1 Year Warranty



Part Number: [M-984-02S](#)

Manufacturer [IXYS Integrated Circuits Division](#)

Description IC TONE DETECTOR MONOLITH 16SOIC

Data sheet:  [M-984-02T](#)

RoHs Status: Lead free / RoHS Compliant

Ship From: Hong Kong






Shipment Way: DHL/Fedex/TNT/UPS/EMS

[Request For Quotation](#)

PRODUCT PARAMETER			
Part Number	M-984-02S	Manufacturer	IXYS Integrated Circuits Division
Description	IC TONE DETECTOR MONOLITH 16SOIC	Lead Free Status / RoHS Status	Lead free / RoHS Compliant
Quantity Available	6024 pcs	Data sheet	M-984-02T
Category	Integrated Circuits (ICs)	Voltage - Supply	2.7 V ~ 5.5 V
Supplier Device Package	16-SOIC	Series	-
Packaging	Tube	Package / Case	16-SOIC (0.295", 7.50mm Width)
Operating Temperature	-40°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Lead Free Status / RoHS Status	Lead free / RoHS Compliant	Interface	-
Includes	-	Function	Tone Detector
Detailed Description	Telecom IC Tone Detector 16-SOIC	Current - Supply	15mA

Component-World.com is a Reliable Stocking Distributor of Electronic Components. We specialize in all IXYS Integrated Circuits Division series electronic components. We have 6024 pieces of IXYS Integrated Circuits Division M-984-02S in stock available now. Request a quote from electronics components distributor at Component-World.com, our sales team will contact you within 24 hours.

RFQ Email: info@Components-World.com

RELATED PRODUCTS			
	Part#: M-985 Description: EARMUFF ASSEMBLY M-985/37333	Manufacturers: 3M	RFQ
	Part#: M-986-2R2PL Description: IC TRANSCEIVER MFC 2CHAN 44-PLCC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-982-02T Description: IC TONE DETECTOR 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-986-2R2P Description: IC TRANSCEIVER MFC 2CHAN 40-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-960 Description: REPLACEMENT VISOR PIVOT KIT M-96	Manufacturers: 3M	RFQ
	Part#: M-985-01T Description: IC TONE DETECTOR PREC 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-982-02S Description: IC TONE DETECTOR 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-984-02T Description: IC TONE DETECTOR MONOLITH 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-985-01S Description: IC TONE DETECTOR PREC 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-986-2A1P Description: IC TRANSCEIVER MF 2CHAN 40-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-980-02P Description: IC TONE DETECTOR GEN PURP 8-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-972 Description: FLAME RESISTANT HEADGEAR COVER M	Manufacturers: 3M	RFQ
	Part#: M-984-02P Description: IC TONE DETECTOR MONOLITH 14-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-982-02P Description: IC TONE DETECTOR SPECIAL 22-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-987-2A1K Description: IC TRANSCEIVER MF 2CH 144-TQFP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-980-02S Description: IC TONE DETECTOR 3V/5V 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-986-2A1PL Description: IC TRANSCEIVER MF 2CHAN 44-PLCC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-985-01P Description: IC TONE DETECTOR PREC 22-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-976 Description: HEAD NECK AND SHOULDER COVER M-9	Manufacturers: 3M	RFQ
	Part#: M-980-02T Description: IC TONE DETECTOR 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ

Related keywords for M-984-02S			
IXYS Integrated Circuits Division M-984-02S	M-984-02S distributor	M-984-02S supplier	M-984-02S price
M-984-02S download datasheet	M-984-02S datasheet	M-984-02S stock	buy M-984-02S
IXYS Integrated Circuits Division M-984-02S			