

CDCV857BIDGG



COMPONENTS-WORLD.COM

Part Number: CDCV857BIDGG

Manufacturer N/A

Description IC SSTL-II PLL CLK-DRVR 48-TSSOP

Data sheet:

RoHs Status: Lead free / RoHS Compliant

Ship From: Hong Kong

Shipment Way: DHL/Fedex/TNT/UPS/EMS

Images are for reference only.
See Product Specifications for product details.
Buy CDCV857BIDGG with confidence from Component-World.HK, 1 Year Warranty

Request For Quotation

PRODUCT PARAMETER			
Part Number	CDCV857BIDGG	Manufacturer	N/A
Description	IC SSTL-II PLL CLK-DRVR 48-TSSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant
Quantity Available	9818 pcs	Data sheet	
Category	Integrated Circuits (ICs)	Voltage - Supply	2.3 V ~ 2.7 V
Type	PLL Clock Driver	Supplier Device Package	48-TSSOP
Series	-	Ratio - Input:Output	1:10
Packaging	Tube	Package / Case	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass	Output	Clock
Other Names	296-13857-5	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	2 (1 Year)	Lead Free Status / RoHS Status	Lead free / RoHS Compliant
Input	Clock	Frequency - Max	200MHz
Divider/Multiplier	No/No	Differential - Input:Output	Yes/Yes
Base Part Number	CDCV857		

Component-World.com is a Reliable Stocking Distributor of Electronic Components. We specialize in all series electronic components. We have 9818 pieces of CDCV857BIDGG in stock available now. Request a quote from electronics components distributor at Component-World.com, our sales team will contact you within 24 hours.
RFQ Email: info@Components-World.com

RELATED PRODUCTS			
	Part#: CDCVF111FNR Description: IC CLK BUFFER 1:9 650MHZ 28PLCC	Manufacturers: N/A	RFQ
	Part#: CDCV857ADGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BIDGGG4 Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857AGQLR Description: IC SSTL-II PLL CLK-DRVR 56-BGA	Manufacturers: N/A	RFQ
	Part#: CDCV857BDGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BGQLR Description: IC 2.5V PLL CLOCK DRVR 56-BGA	Manufacturers: N/A	RFQ
	Part#: CDCV857ADGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BDGGG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857ADGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BIDGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857DGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857ADGGG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857DGGG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BDGGR Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BDGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857DGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCV857BIDGGR Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCVF111FN Description: IC CLK BUFFER 1:9 650MHZ 28PLCC	Manufacturers: N/A	RFQ
	Part#: CDCV857DGG Description: IC SSTL-II PLL CLK-DRVR 48TSSOP	Manufacturers: N/A	RFQ
	Part#: CDCVF111FNG4 Description: IC CLK BUFFER 1:9 650MHZ 28PLCC	Manufacturers: N/A	RFQ

Related keywords for CDCV857BIDGG

CDCV857BIDGG	CDCV857BIDGG distributor	CDCV857BIDGG supplier	CDCV857BIDGG price
CDCV857BIDGG download datasheet	CDCV857BIDGG datasheet	CDCV857BIDGG stock	buy CDCV857BIDGG