

LM8364BALMFX20



COMPONENTS-WORLD.COM

Part Number: [LM8364BALMFX20](#)

Manufacturer: [N/A](#)

Description: [IC DETECTOR UNDERVOLT 2V SOT23-5](#)

Data sheet:

RoHS Status: [Contains lead / RoHS non-compliant](#)

Ship From: [Hong Kong](#)

Shipment Way: [DHL/Fedex/TNT/UPS/EMS](#)

Images are for reference only.
See Product Specifications for product details.
Buy **LM8364BALMFX20** with confidence from
Component-World.HK, 1 Year Warranty

Request For Quotation

PRODUCT PARAMETER			
Part Number	LM8364BALMFX20	Manufacturer	N/A
Description	IC DETECTOR UNDERVOLT 2V SOT23-5	Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant
Quantity Available	4448 pcs	Data sheet	
Category	Integrated Circuits (ICs)	Voltage - Threshold	2V
Type	Simple Reset/Power-On Reset	Supplier Device Package	SOT-23-5
Series	-	Reset Timeout	60 μ s Typical Propagation Delay
Reset	Active Low	Packaging	Tape & Reel (TR)
Package / Case	SC-74A, SOT-753	Output	Open Drain or Open Collector
Operating Temperature	-40°C ~ 85°C (TA)	Number of Voltages Monitored	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant	Detailed Description	Supervisor Open Drain or Open Collector 1 Channel SOT-23-5
Base Part Number	LM8364		
Component-World.com is a Reliable Stocking Distributor of Electronic Components. We specialize in all series electronic components. We have 4448 pieces of LM8364BALMFX20 in stock available now. Request a quote from electronics components distributor at Component-World.com, our sales team will contact you within 24 hours. RFQ Email: info@Components-World.com			

RELATED PRODUCTS			
	Part#: LM8364BALMFX27/NOPB Description: IC UNDER VOLTAGE SENS SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8365BALMFX27 Description: IC DETECT UNDERVOLT 2.7V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMFX20/NOPB Description: IC DETECTOR UNDERVOLT 2V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMFX30/NOPB Description: IC DETECTOR UNDERVOLT 3V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8342SD/NOPB Description: IC TFT VCOM CALIBRATOR 10WSON	Manufacturers: N/A	RFQ
	Part#: LM8342SDX/NOPB Description: IC TFT VCOM CALIBRATOR 10WSON	Manufacturers: N/A	RFQ
	Part#: LM8364BALMFX32/NOPB Description: IC UNDER VOLTAGE SENS SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMF32/NOPB Description: IC UNDERVOLT SENSING CIR SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8365BALMF27/NOPB Description: IC DETECT UNDERVOLT 2.7V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8342SD Description: IC TFT VCOM CALIBRATOR 10WSON	Manufacturers: N/A	RFQ
	Part#: LM8364BALMF27/NOPB Description: IC UNDER VOLTAGE SENS SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8342SDX Description: IC TFT VCOM CALIBRATOR 10WSON	Manufacturers: N/A	RFQ
	Part#: LM8364BALMF45/NOPB Description: IC DETECT UNDERVOLT 4.5V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMF30/NOPB Description: IC DETECT UNDERVOLT 3V SOT-23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMF20/NOPB Description: IC DETECT UNDERVOLT 2V SOT-23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMFX45/NOPB Description: IC DETECT UNDERVOLT 4.5V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8365BALMFX22 Description: IC DETECT UNDERVOLT 2.2V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8365BALMF45/NOPB Description: IC DETECT UNDERVOLT 4.5V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8365BALMF22/NOPB Description: IC DETECT UNDERVOLT 2.2V SOT23-5	Manufacturers: N/A	RFQ
	Part#: LM8364BALMF20 Description: IC DETECT UNDERVOLT 2V SOT-23-5	Manufacturers: N/A	RFQ

Related keywords for LM8364BALMFX20			
LM8364BALMFX20	LM8364BALMFX20 distributor	LM8364BALMFX20 supplier	LM8364BALMFX20 price
LM8364BALMFX20 download datasheet	LM8364BALMFX20 datasheet	LM8364BALMFX20 stock	buy LM8364BALMFX20