

M-986-2A1PL





Part Number: [M-986-2A1PL](#)

Manufacturer [IXYS Integrated Circuits Division](#)

Description IC TRANSCEIVER MF 2CHAN 44-PLCC

Data sheet:

RoHs Status: Lead free / RoHS Compliant

Ship From: Hong Kong

Shipment Way: DHL/Fedex/TNT/UPS/EMS

Images are for reference only.
See Product Specifications for product details.
Buy M-986-2A1PL with confidence from Component-World.HK, 1 Year Warranty

[Request For Quotation](#)

PRODUCT PARAMETER			
Part Number	M-986-2A1PL	Manufacturer	IXYS Integrated Circuits Division
Description	IC TRANSCEIVER MF 2CHAN 44-PLCC	Lead Free Status / RoHS Status	Lead free / RoHS Compliant
Quantity Available	4324 pcs	Data sheet	
Category	Integrated Circuits (ICs)	Voltage - Supply	4.75 V ~ 5.25 V
Type	Transceiver	Supplier Device Package	44-PLCC
Series	-	Protocol	-
Packaging	Tube	Package / Case	44-LCC (J-Lead)
Operating Temperature	0°C ~ 150°C	Number of Drivers/Receivers	2/2
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Lead Free Status / RoHS Status	Lead free / RoHS Compliant	Duplex	Full
Detailed Description	2/2 Transceiver Full 44-PLCC	Data Rate	-
Component-World.com is a Reliable Stocking Distributor of Electronic Components. We specialize in all IXYS Integrated Circuits Division series electronic components. We have 4324 pieces of IXYS Integrated Circuits Division M-986-2A1PL in stock available now. Request a quote from electronics components distributor at Component-World.com, our sales team will contact you within 24 hours. RFQ Email: info@Components-World.com			

RELATED PRODUCTS			
	Part#: M-987-2A1KTR Description: IC TRANSCEIVER MF 2CH 144-TQFP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-982-02T Description: IC TONE DETECTOR 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-991 Description: IC GENERATOR TONE LP CMOS 14-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-986-2A1P Description: IC TRANSCEIVER MF 2CHAN 40-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-985 Description: EARMUFF ASSEMBLY M-985/37333	Manufacturers: 3M	RFQ
	Part#: M-987-2A1K Description: IC TRANSCEIVER MF 2CH 144-TQFP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-980-02S Description: IC TONE DETECTOR 3V/5V 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-991-01SM Description: IC TONE GENERATR LP CMOS 16-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-991-01SMTR Description: IC TONE GENERATR LP CMOS 16-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-984-02T Description: IC TONE DETECTOR MONOLITH 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-984-02S Description: IC TONE DETECTOR MONOLITH 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-980-02T Description: IC TONE DETECTOR 16SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-982-02S Description: IC TONE DETECTOR 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-984-02P Description: IC TONE DETECTOR MONOLITH 14-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-982-02P Description: IC TONE DETECTOR SPECIAL 22-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-986-2R2P Description: IC TRANSCEIVER MFC 2CHAN 40-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-985-01P Description: IC TONE DETECTOR PREC 22-DIP	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-986-2R2PL Description: IC TRANSCEIVER MFC 2CHAN 44-PLCC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-985-01S Description: IC TONE DETECTOR PREC 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ
	Part#: M-985-01T Description: IC TONE DETECTOR PREC 20-SOIC	Manufacturers: IXYS Integrated Circuits Division	RFQ

Related keywords for **M-986-2A1PL**

IXYS Integrated Circuits Division M-986-2A1PL	M-986-2A1PL distributor	M-986-2A1PL supplier	M-986-2A1PL price
M-986-2A1PL download datasheet	M-986-2A1PL datasheet	M-986-2A1PL stock	buy M-986-2A1PL
IXYS Integrated Circuits Division M-986-2A1PL			